

LEYLAND-TRIUMPH SALES COMPANY, INC.

**WESTERN ZONE**



TO: ALL TRIUMPH DEALERS - WESTERN ZONE

DEPT: SERVICE DEPARTMENT AND PARTS DEPARTMENT

BULLETIN T-65-45

SUBJECT: CRANKSHAFT THRUST WASHERS  
SPITFIRE & HERALD MODELS

DATE: OCTOBER 21, 1965

---

It is brought to your attention that when replacing the crankshaft thrust washers on the Herald and Spitfire models, they should be replaced with white metal type, part No. 104820, and not the later type, 141207.

Any existing stocks of Part No. 141207 should be scrapped.

Please treat this information with priority and ensure that your Service and Parts personnel are informed at the earliest opportunity.