

# TECHNICAL SERVICE BULLETIN

NO.



# Triumph

December, 1977

SUBJECT:

EXHAUST MOUNTING RUBBERS


MODELS:

TR7

Complaints have been received of the rubber support rings on the rear exhaust silencer becoming detached from the supporting hooks. The left hand rear chassis side member welded bracket has now been modified as shown in the diagram marked 'A'.

The modification was introduced in production at VIN #ACW 32113. In the event that this complaint is encountered, it will be necessary to re-set the supporting hooks as illustrated.

A warranty time of 00.50 hours will be allowed for this operation.



CHASSIS