

SERVICE & PARTS TECHNICAL INFORMATION

NO.



Triumph

December, 1979

SUBJECT:

EXHAUST SOUND - GEAR CHANGE

MODELS:

TR 7

Current TR 7 vehicles have a tendency to make a popping sound in the exhaust during gear change up shifts.

This condition is more audible under harsh acceleration and should be considered as a normal operating condition.

Warranty claims for attempted rectification must not be submitted.

H.C.T.