

SERVICE INFORMATION



STANDARD AND TRIUMPH VEHICLES

(NOT FOR PUBLICATION)

No.	SPORTS/8/E	GEARBOX RUBBER GROMMET	Date	FEBRUARY 1955
------------	------------	------------------------	-------------	---------------

Following investigation of a few cases of damage by ripping, the original rubber Gearbox Grommet, Part No. 70853, has been re-designed to provide a greater degree of flexibility and in addition is now manufactured of a harder rubber.

The new grommet is supplied under Part No. 603065, and was introduced in normal manufacture at Gearbox No. TS.5736 although this change was anticipated on Gearbox Nos. TS.5752, TS.5734, TS.5723, T.S.5711, TS.5730 and TS.4854. The approximate Commission No. at which this grommet was introduced in normal manufacture was TS.5352.