

LEYLAND-TRIUMPH SALES COMPANY, INC.

WESTERN ZONE



TO: ALL TRIUMPH DEALERS - WESTERN ZONE

DEPT: SERVICE DEPARTMENT

BULLETIN T-65-36

SUBJECT: TRAFFIC INDICATOR SWITCHES
HERALD, SPORTS SIX, SPITFIRE
AND TR-4

DATE: AUGUST 26, 1965

A modified flasher indicator switch, part number 140626, now replaces the original switch, part number 131274, for 1200, Spitfire and Sports Six models.

Although a single lobed cancelling cam 140549 is fitted with the new switch on production, the original double lobed cam 122525 can be retained on the car in service.

For NON-current models, i.e. 948 Herald, the latest type switch with a grey colored lever will be supplied under part number 128521.

The current switch for the TR-4A, part number 141628, will be supplied in place of 129891 for the TR-4 as they are interchangeable.

It is essential that when fitting the latest switch, the two shorter screws packed with the switch must be fitted in place of existing screws, as the original screws will foul the internal mechanism and damage the switch.