

STANDARD-TRIUMPH MOTOR COMPANY, INC.
WESTERN ZONE



TO: ALL TRIUMPH DEALERS - WESTERN ZONE

DEPT: SERVICE AND PARTS

BULLETIN T-63-55

SUBJECT: SPITFIRE HEATER HOSES

DATE: AUGUST 22, 1963

At Commission Number FC-8274, a moulded rubber hose replaced the canvas hose between the heater water valve at the bulkhead and the cylinder block.

Please notify your Service Department that Spitfire cars between Commission Number FC-8274 and FC-10950, when in for service or otherwise available, to ensure that the hose is not fouling the oil filler/breather cap.

Where fouling occurs, slacken the Jubilee Clip at the water valve and reset the hose to give adequate clearance.