

TECHNICAL SERVICE BULLETIN

NO.



Triumph

July, 1977

B
E
L
E
C

SUBJECT:

THERMAL CUT-OUT

MODELS:

1977 TR7

Under certain climatic conditions the air conditioning compressor clutch may continue to cycle with abnormal regularity.

Investigation has shown that this usually is associated with a malfunction of the thermal cut-out which is mounted on the relay bracket behind the glove box.

Part #USA 600 is a suitable substitute, however, it is necessary to remove the mounting plate. This is best achieved by cutting the bracket flush with the side of the thermal cut-out which then allows it to snap into the receptacle on the relay mounting plate.

J.P.