

# SERVICE & PARTS TECHNICAL INFORMATION

NO.



# Triumph

April, 1979

SUBJECT:

AIR CONDITIONING CONDENSATE DRAIN

MODELS:

TR7

It is possible that a condition could exist whereby condensation may drain into the footwells on either side of the air conditioning unit.

To rectify any complaints resulting from this condition a Drip Tray Drain Kit, part no. BLM 601038, must be fitted. A time of .60 hours is allowed for this operation.

A copy of the installation instructions enclosed with each kit is attached to this bulletin.

Attachment  
P.W.B./H.C.T.