

LEYLAND-TRIUMPH SALES COMPANY, INC.

WESTERN ZONE



TO: ALL TRIUMPH DEALERS - WESTERN ZONE

DEPT: SERVICE DEPARTMENT

BULLETIN T-67-13

SUBJECT: GEARBOX NOISE - GT-6

DATE: FEBRUARY 16, 1967

Should complaints be received of a noise in first gear, caused by the touching of first and reverse gears, a modified selector shaft and reverse actuator must be fitted.

The fitting of the parts will necessitate removal and stripping down of the gearbox lid.

The parts required from Spares Division are:

Selector shaft	Part number 147395
Reverse actuator	Part number 147394

The above parts were incorporated at approximately KC/503 (GT-6).