

TECHNICAL SERVICE BULLETIN

NO.



Triumph

April, 1977

B
E
L
E
C

SUBJECT:

HEAD LAMP FEED WIRE SECURITY

MODELS:

TR7

When installing head lamp assemblies on the TR7, extra care should be taken to insure that the lamp feed wire is routed in such a manner so as to prevent it from becoming trapped in the closed position, between the top of the actuating motor and the base of the lamp tray assembly (refer to diagram).

continued.....

