


LEYLAND-TRIUMPH SALES COMPANY, INC.

WESTERN ZONE



TO: ALL TRIUMPH DEALERS - WESTERN ZONE

ATTN: SERVICE & PARTS

BULLETIN T-64-16

SUBJECT: TRIUMPH 1200, SPITFIRE AND
SPORTS SIX VALVE SPRINGS

DATE: MAY 29.1964

With the introduction of the single heavier valve springs in place of the double springs, it is essential that correct replacements are fitted when necessary.

The outer spring, 121251, must not be used as a single spring to replace 136487 and conversely 136487 must not be used in place of 121251 with inner spring 102564.

Both items should be segregated under the respective part numbers in your Parts Department.

PLEASE ENSURE THAT ALL PARTS DEPARTMENTS ARE ALERTED TO THIS IMPORTANT INFORMATION.