

SERVICE INFORMATION



STANDARD AND TRIUMPH VEHICLES

(NOT FOR PUBLICATION)

No.	SPORTS/1/C	RADIATOR BLOCK AND THERMOSTAT HOUSING	Date	JUNE 1954
------------	------------	---------------------------------------	-------------	-----------

The Thermostat Housing, Part No. 201522, was replaced by Part No. 202033 for convenience of manufacture. This change was incorporated at Commission No. TS.1201.

When the new Thermostat Housing was introduced the water outlet was off-set from the centre line and the original Radiator, Part No. 400311, was replaced by Radiator, Part No. 400412.

The Thermostat Element, Part No. 107590, the Top Water Hose, Part No. 101571, and By Pass Hose, Part No. 105598, are unaffected by this change.

The Bottom Water Pipe Assembly of Rubber Hose, Part No. 107292 (2 off) and steel Connection Pipe, Part No. 201795, fitted up to Commission No. TS.414, or the later Assembly of Rubber Hose, Part No. 108422 (2 off) and steel Connection Pipe, Part No. 108423, are also unaffected by this change of Thermostat Housing and Radiator Block.

NOTE: These instructions are for information only and do not constitute an authority to carry out modifications at the expense of The Standard Motor Company Limited.

This Sheet gives Important service Information and should be filed by your Service Dept. in the Service Information Folder.
