

TECHNICAL SERVICE BULLETIN

77-B-9

NO.



Triumph

August, 1977

B
E
L
E
C

SUBJECT:

REVISED HORN RELAY

MODELS:

TR7

A new improved horn relay was introduced at VIN #ACW10719. The part number of the new relay is DRC131.

T-09-77/114