

STANDARD-TRIUMPH MOTOR COMPANY, INC.

WESTERN ZONE



TO: ALL TRIUMPH DEALERS - WESTERN ZONE

DEPT: SERVICE & PARTS

BULLETIN T-63-66

SUBJECT: SMALL CAR MODELS
DIFFERENTIAL DRAIN PLUG

DATE: NOVEMBER 1, 1963

The rear axle differential case drain plug has been deleted from production on the Herald, Spitfire and Sports Six.

In future service requirements for the differential unit are reduced to topping up to correct level. Draining and refilling will not be necessary.

Drain plugs will be retained in gearboxes for these models but service requirements will be reduced to topping up rather than drain and refill.

Future maintenance instructions will be suitably amended.