

TECHNICAL SERVICE BULLETIN

NO.



Triumph

January, 1977

SUBJECT:

SPARK PLUG SPECIFICATION 1977 MODEL

MODELS:

TR7

The initial supply of 1977, 49 states only, TR7s will be equipped with Champion N11Y spark plugs. Later production will revert back to N12Y.

It should be noted that the N11Y plug is perfectly satisfactory, however, in the event that replacement is required, N12Y may be substituted.

This bulletin is for your information only.

D.B.